


INDUSTRIAL THERMOCOUPLES

Base Metal Bare Thermocouple Elements



Steps: **A** **B** **C** **D**

Model: **Q1** — — —

A	Junction Weld Description
A	Butt-weld
B	Parallel-weld
C	Twist-weld

C Calibration			
Standard Limits of Error		Special Limits of Error	
A	J	C	J
B	K	D	K

D	"U" Dimension
	Specify "U" Length In Inches <u>0 1 8</u>

Example "U" is 18" = 018

B	Thermocouple Wire Gage	
<u>Model</u>	<u>Wire Gage</u>	<u>Description</u>
1	8	No Ceramic Insulators, Bare Thermocouple Element
2	14	No Ceramic Insulators, Bare Thermocouple Element
3	20	No Ceramic Insulators, Bare Thermocouple Element