


# NOBEL METAL THERMOCOUPLES

## Bare Element Thermocouples

Model: **T1**



Steps:      **A**      **B**      **C**

Model: **T1**            —            —     

<b>A</b>	<b>Wire Gage</b>
<b>A</b>	20 Gage
<b>B</b>	24 Gage
<b>C</b>	26 Gage
<b>D</b>	28 Gage

<b>B</b>		<b>Calibration</b>	
Standard Limits of Error		Special Limits of Error	
<b>A</b>	<b>S</b>	<b>D</b>	<b>S</b>
<b>B</b>	<b>R</b>	<b>E</b>	<b>R</b>
<b>C</b>	<b>B</b>	<b>F</b>	<b>B</b>

<b>C</b>	<b>"U" Dimension</b>
Specify "U" Length In Inches <u>0 1 8</u>	
Example "U" is 18" = 018	